

Dot Matrix Replacement Guide



A cross reference guide designed to help you quickly find replacements for older printers.

STEP 1: Quickly find your older printer by manufacturer and model number

STEP 2: Cross reference the recommended replacement

1-877-434-1377

DASCOM

Popular Tally printers from DASCAM



T2380 1000 cps



T2365 840 cps



T2265 720 cps



T2150 720 cps



T2250 720 cps



T2440 576 cps



T2240 500 cps



LA48N 400 cps

TABLE OF CONTENTS

CONTENTS

AMT & AT&T REPLACEMENTS	4
BROTHER, CITIZEN, & DATAPRODUCTS REPLACEMENTS.....	5
DATASOUTH & DEC REPLACEMENTS.....	6
EPSON & FACIT	7
EPSON (CONT'D) & FUJITSU.....	8
GENICOM	9
IBM/INFOPRINT, LEXMARK & NEC.....	10
OKIDATA, OTC & PANASONIC	11
PRINTEK, SEIKOSHA & TI.....	12
TALLY	13
UNISYS	14

AMT & AT&T REPLACEMENTS

AMT			
Model	Speed (CPS) @ 10 CPI	Pins	Tally Replacement
Accel-212	200	9	<u>T2240/9</u>
Accel-214	200	24	<u>T2340/24</u>
Accel-244	225	24	<u>T2340/24</u>
Accel-292	480	9x2	<u>T2340/24, T2150</u>
Accel-294	480	9x2	<u>T2250</u>
Accel-342	320	24	<u>T2240/24</u>
Accel-344	320	24	<u>T2340/24</u>
Accel-535	400	24	<u>T2250</u>
Accel-5350	480 @ 12	24	<u>T2265, T2365</u>
Accel-6310	600 @ 12	24	<u>T2265, T2365</u>
Accel-6350	600 @ 12	24	<u>T2265, T2365</u>
DM3300	333 @ 12	9	<u>T2240/9</u>
DM6300	622 @ 12	18	<u>T2265, T2365</u>
PP405	600	24	<u>T2265, T2365</u>
XL300	300	9	<u>T2250</u>
CL400	400	18	<u>T2250</u>

AT&T			
Model	Speed (CPS) @ 10 CPI	Pins	Tally Replacement
570	250	9	<u>T2340/24</u>
571	250	9	<u>T2340/24</u>
572	250	9	<u>T2340/24</u>
573	250	9	<u>T2340/24</u>
577	450	18	<u>T2250</u>
580	200	24	<u>T2340/24</u>
581	200	24	<u>T2340/24</u>
583	200	24	<u>T2340/24</u>

BROTHER, CITIZEN, & DATAPRODUCTS REPLACEMENTS

Brother			
Model	Speed (CPS) @ 10 CPI	Pins	Tally Replacement
M-1309	180	9	<u>T2240/9</u>
M-1324	180	24	<u>T2240/24</u>
M-1809	300	18	<u>T2240/9</u>
M-1824L	225	24	<u>T2240/24</u>
M-1909	300	18	<u>T2340/24</u>
M-1924L	225	24	<u>T2340/24</u>
M-2518	300	18	<u>T2340/24</u>
M-4018	400	18	<u>T2250</u>
M-4309A	600	18	<u>T2265, T2365</u>
XL-500	180	9	<u>T2240/9</u>
XL-1500	180	24	<u>T2240/24</u>
Dataproducts			
Model	Speed (CPS) @ 10 CPI	Pins	Tally Replacement
8070	480	18	T2245
8500	520	18	<u>T2265, T2365</u>
9030	250	9	<u>T2240/9</u>
9034	250	24	<u>T2240/24</u>
9040	250	9	<u>T2340/24</u>
9044	250	24	<u>T2340/24</u>

Citizen			
Model	Speed (CPS) @ 10 CPI	Pins	Tally Replacement
120D	120	9	<u>T2240/9</u>
GSX-140	160	24	<u>T2240/24</u>
GSX-140+	180	24	<u>T2240/24</u>
GSX-145	160	24	<u>T2340/24</u>
GSX-190	240	9	<u>T2240/9</u>
GSX-230	194	24	<u>T2240/24</u>
GSX-240	215	24	<u>T2240/24</u>
200GX	213	9	<u>T2240/9</u>
200GX	213	9	<u>T2340/24</u>
HSP-500	250	9	<u>T2340/9</u>
HSP-550	250	9	<u>T2340/24</u>

DATASOUTH & DEC REPLACEMENTS

Datasouth			
Model	Speed (CPS) @ 10 CPI	Pins	Tally Replacement
XL300	300	9	<u>T2250</u>
XL400	400	18	<u>T2250</u>
CX3180	180	9	<u>T2340/24</u>
CX3220	220	9	<u>T2340/24</u>
CX3400	400	18	<u>T2250</u>
DS180+	180	9	<u>T2340/24</u>
DS220	220	9	<u>T2340/24</u>
DS400	400	18	<u>T2250</u>
Dmax 300	250	9	<u>T2240/9</u>
Pmax A600	622	18	<u>T2265, T2365</u>
TX5180	180	9	<u>T2340/24</u>
TX5400	400	18	<u>T2250</u>

DEC			
Model	Speed (CPS) @ 10 CPI	Pins	Tally Replacement
LA100	240	9	<u>LA48W</u>
LA120	120	-	<u>LA48N/W</u>
LA180	180	-	<u>LA48N/W</u>
LA195	240	24	<u>LA48W</u>
LA210	240	9	<u>LA48W</u>
LA30N	333	24	<u>LA48N/W</u>
LA30W	300	24	<u>LA48W</u>
LA310	240	9	<u>LA48W</u>
LA324	300	24	<u>LA48W</u>
LA34	30	24	<u>LA48N/W</u>
LA36	360	24	<u>LA48N/W</u>
LA36N-W	360	24	<u>LA48N/W</u>
LA400	400	24	<u>LA48W</u>
LA424	400	24	<u>LA48W</u>
LA450	450	24	<u>LA500</u>
LA50	100	-	<u>LA48N</u>
LA600	600	24	<u>LA650</u>
LA65	160	24	<u>LA48N</u>
LA70	200	9	<u>LA48N</u>
LA700	700	9	<u>LA800</u>
LA75	240	9	<u>LA48N</u>
LA75S	250	24	<u>LA48N</u>
LA75S	250	24	<u>LA48N</u>

EPSON & FACIT

Epson			
Model	Speed (CPS) @ 10 CPI	Pins	Tally Replacement
DFX5000	533	9	<u>T2265, T2365</u>
DFX8000	800	9	<u>T2280, T2380</u>
FX850	220	9	<u>T2240/9</u>
FX870	285	9	<u>T2240/9</u>
FX880	440	9	<u>T2150</u>
FX980	506	9	<u>T2265, T2365</u>
FX1050	220	9	<u>T2340/24</u>
FX1170	285	9	<u>T2340/24</u>
FX1180	440	9	<u>T2250</u>
FX2180	500	9	<u>T2265, T2365</u>
LQ200	160	24	<u>T2240/24</u>
LQ510	150	24	<u>T2240/24</u>
LQ570	210	24	<u>T2240/24</u>
LQ680	413	24	<u>T2150</u>
LQ850	246	24	<u>T2240/24</u>
LQ860	246	24	<u>T2240/24</u>
LQ870	275	24	<u>T2250/24</u>
LQ1010	150	24	<u>T2340/24</u>
LQ1050	246	24	<u>T2340/24</u>
LQ1070	225	24	<u>T2340/24</u>
LQ1170	275	24	<u>T2340/24</u>

Epson Printers are continued on the next page

Facit			
Model	Speed (CPS) @ 10 CPI	Pins	Tally Replacement
B1200	160	9	<u>T2240/9</u>
B2100	200	9	<u>T2240/9</u>
B2150	200	9	<u>T2340/24</u>
B2400	200	24	<u>T2240/24</u>
B2450	200	24	<u>T2340/24</u>
B3100	250	9	<u>T2240/9</u>
B3100C	250	9	<u>T2340/24</u>
B3450	250	24	<u>T2340/24</u>
B3550	400	18	<u>T2250</u>
D2500	240	24	<u>T2240/24</u>
D2600	240	24	<u>T2340/24</u>
DM 3000	200	9	<u>T2240/9</u>
E620	250	9	<u>T2240/9</u>
E630	250	9	<u>T2340/24</u>
E670	300	24	<u>T2340/24</u>
E7650	400	18	<u>T2250</u>
E950	720	24	<u>T2280, T2380</u>
PP405	600	24	<u>T2265, T2365</u>
PP406	600	24	<u>T2265, T2365</u>
PP408	700	24	<u>T2280, T2380</u>
D2600	240	24	<u>T2340/24</u>
DM 3000	200	9	<u>T2240/9</u>

EPSON (CONT'D) & FUJITSU

Epson - Continued			
Model	Speed (CPS) @ 10 CPI	Pins	Tally Replacement
LQ2080	400	24	<u>T2250</u>
LQ2180	480	24	<u>T2265, T2365</u>
LQ2250	333	24	<u>T2250</u>
LX300	220	9	<u>T2240/9</u>
LX810	200	9	<u>T2240/9</u>

Fujitsu			
Model	Speed (CPS) @ 10 CPI	Pins	Tally Replacement
DL1150	200	24	<u>T2240/24</u>
DL1250	200	24	<u>T2340/24</u>
DL3300	240	24	<u>T2240/24</u>
DL3400	240	24	<u>T2340/24</u>
DL3800	300	24	<u>T2340/24</u>
DL4400	220	24	<u>T2340/24</u>
DL4600	333	24	<u>T2340/24</u>
DL5600	405	24	<u>T2250</u>
DL5800	420	24	<u>T2250</u>
DX2300	270	9	<u>T2240/9</u>
DX2400	270	9	<u>T2340/24</u>

GENICOM

Genicom			
Model	Speed (CPS) @ 10 CPI	Pins	Tally Replacement
930	390	9	<u>T2150</u>
935	390	9	<u>T2250</u>
1020	200	18	<u>T2340/24</u>
1025	200	18	<u>T2250</u>
1040	360	24	<u>T2250</u>
1220	300	24	<u>T2340/24</u>
3210	240	9	<u>T2340/24</u>
3320	300	18	<u>T2340/24</u>
3405	400	18	<u>T2150</u>
3410XLS	400	18	<u>T2250</u>
3510	300	9	<u>T2340/24</u>
3520	300	9	<u>T2340/24</u>
3530	400	18	<u>T2250</u>
3540	400	18	<u>T2250</u>
3610-201	300	9	<u>T2340/24</u>
2420-101	300	9	<u>T2340/24</u>

Genicom			
Model	Speed (CPS) @ 10 CPI	Pins	Tally Replacement
3630-202	400	18	<u>T2250</u>
3640-102	400	18	<u>T2250</u>
3811	1100	18	<u>T2280, T2380</u>
3810	500	18	<u>T2265, T2365</u>
3830	500	18	<u>T2265, T2365</u>
3840	500	18	<u>T2265, T2365</u>
3850	500	24	<u>T2265, T2365</u>
3860	600	18	<u>T2265, T2365</u>
3870	750	18	<u>T2265, T2365</u>
3880	800	18	<u>T2280, T2380</u>
3930	500	18	<u>T2265, T2365</u>
3940	500	18	<u>T2265, T2365</u>
3972	750	18	<u>T2280, T2380</u>

IBM/INFOPRINT, LEXMARK & NEC

IBM/Infoprint			
Model	Speed (CPS) @ 10 CPI	Pins	Tally Replacement
2380	270	9	<u>T2240/9</u>
2381	270	9	<u>T2340/24</u>
2390	180	24	<u>T2240/24</u>
2391	180	24	<u>T2340/24</u>
4201	270	9	<u>T2240/9</u>
4202	270	9	<u>T2340/24</u>
4207	240	24	<u>T2240/24</u>
4208	240	24	<u>T2340/24</u>
4210	200	9	<u>T2340/24</u>
4212	160	24	<u>T2240/24</u>
4224-01	200	9	<u>T2340/24</u>
4224-02	400	18	<u>T2250</u>
4224-03	600	18	<u>T2265, T2365</u>
4226-302	400	9	<u>T2250</u>
4230	400	9	<u>T2250</u>
4232	400	9	<u>T2250</u>
4247-L03	600	24	<u>T2365</u>
4247-X03	800	24	<u>T2380</u>
4247-Z03	1100	24	<u>T2380</u>
5204	330	24	<u>T2340/24</u>

Lexmark			
Model	Speed (CPS) @ 10 CPI	Pins	Tally Replacement
2380	270	9	<u>T2240/9</u>
2381	270	9	<u>T2340/24</u>
2390	210	24	<u>T2240/24</u>
2391	210	24	<u>T2340/24</u>
2480	438	9	<u>T2240/9</u>
2481	348	9	<u>T2340/24</u>
2490	409	24	<u>T2240/24</u>
2491	409	24	<u>T2340/24</u>
4226	400	9	<u>T2250</u>
4226	400	9	<u>T2250</u>

NEC			
Model	Speed (CPS) @ 10 CPI	Pins	Tally Replacement
P1200	160	24	<u>T2240/24</u>
P2200	140	24	<u>T2240/24</u>
P5200	220	24	<u>T2240/24</u>
P5300	220	24	<u>T2340/24</u>
P6200	250	24	<u>T2240/24</u>
P6300	250	24	<u>T2340/24</u>
P3300	180	24	<u>T2340/24</u>
P9300	333	24	<u>T2340/24</u>

OKIDATA, OTC & PANASONIC

Okidata			
Model	Speed (CPS) @ 10 CPI	Pins	Tally Replacement
180	120	9	<u>T2240/9</u>
ML172	120	9	<u>T2240/9</u>
ML180T	155	9	<u>T2240/9</u>
ML184T	200	9	<u>T2240/9</u>
ML320	300	9	<u>T2240/9</u>
ML321	300	9	<u>T2340/24</u>
ML380	150	24	<u>T2240/24</u>
ML390+	225	24	<u>T2240/24</u>
ML391+	225	24	<u>T2340/24</u>
ML393+	346	24	<u>T2340/24</u>
ML395	405	24	<u>T2150</u>
ML420	510	9	<u>T2150</u>
ML421	510	9	<u>T2250</u>
ML490	420	24	<u>T2240/24</u>
ML491	420	24	<u>T2340/24</u>
ML520	320	9	<u>T2150</u>
ML521		9	<u>T2250</u>
ML590	300	24	<u>T2150</u>
ML591	300	24	<u>T2250</u>
240	150	24	<u>T2240/24</u>
PM2140	350	9	<u>T2340/24</u>
PM3410	417	9	<u>T2250</u>
PM4410	1066	18	<u>T2280, T2380</u>

OTC			
Model	Speed (CPS) @ 10 CPI	Pins	Tally Replacement
560	362	9 x 2	<u>T2250</u>
850XL	800	9 X 3	<u>T2280, T2380</u>
888XL-2	8009 X3	9 X 3	<u>T2280, T2380</u>
889XL-2	800	9 X 3	<u>T2280, T2380</u>
MTP	600	9	<u>T2265, T2365</u>

Panasonic			
Model	Speed (CPS) @ 10 CPI	Pins	Tally Replacement
KX-P1150	160	9	<u>T2240/9</u>
KX-P1180	160	9	<u>T2240/9</u>
KX-P1191	200	9	<u>T2240/9</u>
LX-P1624	160	24	<u>T2340/24</u>
KX-P1654	250	24	<u>T2340/24</u>
KX-P1695	275	9	<u>T2340/24</u>
KX-P2023	160	24	<u>T2240/24</u>
KX-P2123	160	24	<u>T2240/24</u>
KX-P2124	213	24	<u>T2240/24</u>
KX-P2624	200	24	<u>T2340/24</u>
KX-P3123	160	24	<u>T2240/24</u>
KX-P3124	213	24	<u>T2240/24</u>
KX-P3624	200	24	<u>T2340/24</u>

PRINTEK, SEIKOSHA & TI

Printek			
Model	Speed (CPS) @ 10 CPI	Pins	Tally Replacement
930DLX	200	9	<u>T2340/24</u>
FM8000	800	18	<u>T2280, T2380</u>
FP2000	200	9	<u>T2340/24</u>
FP4000	400	18	<u>T2265, T2365</u>
FP4300	225	9	<u>T2265, T2365</u>
FP4500	530	9	<u>T2265, T2365</u>
FP4600	600	9	<u>T2265, T2365</u>
PM850	530	18	<u>T2265, T2365</u>
PM852	530	18	<u>T2265, T2365</u>
TI			
Model	Speed (CPS) @ 10 CPI	Pins	Tally Replacement
810	150	7	<u>T2340/24</u>
820	150	9	<u>T2340/24</u>
830	300	9	<u>T2240/9</u>
835	300	9	<u>T2340/24</u>
880	300	9	<u>T2340/24</u>
885	300	9	<u>T2240/9</u>
8920	400	18	<u>T2250</u>
8930	400	18	<u>T2250</u>

Seikosha			
Model	Speed (CPS) @ 10 CPI	Pins	Tally Replacement
PB-5460	460	8	T2250
BP-5780	520	18	<u>T2265, T2365</u>
LT-20	120	24	<u>T2240/24</u>
P900	160	9	<u>T2240/9</u>
P2400	200	24	<u>T2240/24</u>
P2400	200	24	<u>T2240/24</u>
SB-10+	800	18	<u>T2280, T2380</u>
SK-3000AI	300	9	<u>T2240/9</u>
SK-3005+	300	9	<u>T2240/24</u>
SL-90+	200	24	<u>T2240/24</u>
SL-270	274	24	<u>T2340/24</u>
SP-2000+	160	9	<u>T2240/9</u>
SP2000AP	120	9	<u>T2240/9</u>
SP-2000S	160	9	<u>T2240/9</u>
SP-2400	200	9	<u>T2240/9</u>
SP-2415	200	9	<u>T2340/24</u>
SP-2450	180	9	<u>T2240/9</u>

TALLY

Tally			
Model	Speed (CPS) @ 10 CPI	Pins	Tally Replacement
MT81	130	9	<u>T2240/9</u>
MT82	160	24	<u>T2240/24</u>
MT87	200	9	<u>T2240/9</u>
MT88	200	9	<u>T2340/24</u>
MT130/9	300	9	<u>T2340/24</u>
MT130/24	250	24	<u>T2340/24</u>
MT131/9	300	9	<u>T2340/24</u>
MT131/24	250	24	<u>T2340/24</u>
MT150/9	250	9	<u>T2240/9</u>
MT150/24	300	24	<u>T2240/24</u>
MT150/9	250	9	<u>T2240/9</u>
MT150/24	300	24	<u>T2240/24</u>
MT151/9	250	9	<u>T2240/9</u>
MT151/24	300	24	<u>T2340/24</u>
MT220	24	24	<u>T2340/24</u>
MT230/9	300	9	<u>T2340/24</u>
MT230/24	300	24	<u>T2340/24</u>
MT290	200	9	<u>T2340/24</u>

Tally			
Model	Speed (CPS) @ 10 CPI	Pins	Tally Replacement
MT330	300	24	<u>T2340/24</u>
MT340	400	18	<u>T2250</u>
MT350	450	24	<u>T2250</u>
MT360	600	24	<u>T2265, T2365</u>
MT3860	720	24	<u>T2265, T2365</u>
MT460D	270	9	<u>T2265, T2365</u>
MT490	400	18	<u>T2265, T2365</u>
T2030/9	360	9	<u>T2240/9</u>
T2030/24	330	24	<u>T2240/24</u>
T2040	400	24	<u>T2150</u>
T2045	450	24	<u>T2250</u>
T2060	600	2	<u>T2265, T2365</u>
T2130/9	360	9	<u>T2340/24</u>
T2130/24	330	24	<u>T2340/24</u>
T2140	400	24	<u>T2250</u>
T2155	550	24	<u>T2265, T2365</u>
T2170	700	24	<u>T2280, T2380</u>

Unisys			
Model	Speed (CPS) @ 10 CPI	Pins	Tally Replacement
AP1324	333	24	<u>T2340/24</u>
AP1327	270	9	<u>T2240/9</u>
AP1329	270	9	<u>T2340/24</u>
AP1337	225	24	<u>T2240/24</u>
AP1357	300	24	<u>T2240/24</u>
AP1359	300	24	<u>T2340/24</u>
AP1371	600	18	<u>T2265, T2365</u>